

# FACILITY CONDITION ASSESSMENT

*Prepared for*

Ann Arbor Public Schools  
2555 South State Street  
Ann Arbor, Michigan 48104  
Jim Vibbart



FACILITY CONDITION ASSESSMENT

OF

LAWTON ELEMENTARY  
2250 SOUTH SEVENTH STREET  
ANN ARBOR, MICHIGAN 48103

**PREPARED BY:**

*EMG*

*10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.emgcorp.com](http://www.emgcorp.com)*

**EMG CONTACT:**

*Andrew Hupp  
Program Manager  
800.733.0660 x6632  
[ahupp@emgcorp.com](mailto:ahupp@emgcorp.com)*

**EMG PROJECT #:**

*129010.18R000-016.354*

**DATE OF REPORT:**

*June 29, 2018*

**ONSITE DATE:**

*March 9, 2018*



engineering | environmental | capital planning | project management

EMG Corporate Headquarters 10461 Mill Run Circle, Suite 1100, Owings Mills, MD 21117 [www.EMGcorp.com](http://www.EMGcorp.com) p 800.733.0660

**Immediate Repairs Report**  
**Lawton Elementary School**  
**6/29/2018**



<b>EMG Renamed Item Number</b>	<b>Location Description</b>	<b>ID</b>	<b>Cost Description</b>	<b>Quantity</b>	<b>Unit</b>	<b>Unit Cost *</b>	<b>Subtotal</b>	<b>Deficiency Repair Estimate *</b>
1.2	Throughout	880768	Engineer, Environmental, Asbestos (ACM) & Lead Base Paint (LBP), Evaluate/Report	1	EA	\$5,750.00	\$5,750	<b>\$5,750</b>
D30	Interiors	885588	Air Conditioning, Central, Install	50000	SF	\$11.50	\$575,000	<b>\$575,000</b>
C10	Mechanical room	881201	Interior Wall Finish, Gypsum Board/Plaster, Repair	1500	SF	\$3.66	\$5,488	<b>\$5,488</b>
D20	315	880838	Drinking Fountain, Refrigerated, Replace	1	EA	\$1,446.13	\$1,446	<b>\$1,446</b>
D30	Main roof	881319	Exhaust Fan, Centrifugal, 251 to 800 CFM, Replace	1	EA	\$2,325.15	\$2,325	<b>\$2,325</b>
D50	314	880841	Fluorescent Lighting Fixture, 80 W, Replace	1	EA	\$241.87	\$242	<b>\$242</b>
D50	310	880818	Emergency/Exit Combo LED, Install	1	EA	\$687.51	\$688	<b>\$688</b>
	Site	958707	Davis Bacon Prevailing Wages, Surcharge for Prevailing Wages, 10% surcharge for prevailing wages	50381.02	LS	\$1.15	\$57,938	<b>\$57,938</b>
G20	Parking lot	881529	ADA, Parking, Signage, Pole-Mounted, Install	1	EA	\$500.00	\$500	<b>\$500</b>
D20	Restroom	881532	ADA, Restroom, Lavatory Pipe Wraps, Install	4	EA	\$80.00	\$320	<b>\$320</b>

**Immediate Repairs Total**

**\$649,696**

\* Location Factor (1) included in totals.

Replacement Reserves Report

Lawton Elementary School



6/29/2018

Location	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	Total Escalated Estimate
Lawton Elementary School	\$649,696	\$410,929	\$450,998	\$1,041,181	\$642,570	\$657,355	\$391,559	\$446,511	\$73,394	\$1,466,510	\$1,696,502	\$432,720	\$241,483	\$114,124	\$794,305	\$528,844	\$747,419	\$149,900	\$361,407	\$807,557	\$12,104,965
<b>GrandTotal</b>	<b>\$649,696</b>	<b>\$410,929</b>	<b>\$450,998</b>	<b>\$1,041,181</b>	<b>\$642,570</b>	<b>\$657,355</b>	<b>\$391,559</b>	<b>\$446,511</b>	<b>\$73,394</b>	<b>\$1,466,510</b>	<b>\$1,696,502</b>	<b>\$432,720</b>	<b>\$241,483</b>	<b>\$114,124</b>	<b>\$794,305</b>	<b>\$528,844</b>	<b>\$747,419</b>	<b>\$149,900</b>	<b>\$361,407</b>	<b>\$807,557</b>	<b>\$12,104,965</b>

EMG Renamed Item Number	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	w/ Markup *	Subtotal	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	RRR	RowGrandTotal	Label		
1.2	Throughout	880768	Engineer, Environmental, Asbestos (ACM) & Lead Base Paint (LBP), Evaluate/Report		0	0	1	EA	\$5,000.00	\$5,750.00	\$5,750	\$5,750																					\$5,750			
D30	Interiors	885588	Air Conditioning, Central, Install		50	50	0	50000	SF	\$10.00	\$11.50	\$575,000	\$575,000																					\$575,000		
B20	roof hatches	881324	Structural Flooring/Decking, Metal, Refinish		10	9	1	72	SF	\$1.44	\$1.44	\$104	\$104													\$104								\$207		
B20	multi-purpose room	880735	Exterior Stair/Ramp Rails, Metal, Refinish		10	7	3	100	LF	\$1.44	\$1.44	\$144											\$144					\$144						\$288		
B20	multipurpose room stairs	882808	Exterior Stair/Ramp Rails, Metal, Refinish		10	6	4	100	LF	\$1.44	\$1.44	\$144											\$144					\$144						\$288		
B20	Exterior wall	880616	Exterior Wall, Brick Veneer, 1-2 Stories, Replace		40	38	2	110	SF	\$48.58	\$55.87	\$6,146										\$6,146												\$6,146		
B20	Exterior wall	880614	Exterior Wall, Brick or Brick Veneer, 1-2 Stories, Repoint		25	23	2	1000	SF	\$41.28	\$47.47	\$47,475										\$47,475												\$47,475		
B20	Exterior wall	881520	Exterior Wall, Fascia, door area Paint, Prep & Paint		10	8	2	5000	SF	\$2.87	\$3.30	\$16,507										\$16,507					\$16,507							\$33,013		
B20	Exterior wall	880611	Exterior Wall, Joint Caulking 0" to 1/2", 1-2 Stories, Replace		10	7	3	3500	LF	\$2.82	\$3.24	\$11,351															\$11,351							\$22,701		
B20	314/315	881245	Soffit, Wood, Replace		20	19	1	64	SF	\$17.37	\$19.97	\$1,278	\$1,278																					\$1,278		
B20	Throughout	880753	Window Screen, Aluminum 12 SF, Replace		10	5	5	43	EA	\$518.50	\$596.28	\$25,640																						\$25,640		
B20	Throughout	880754	Window, Aluminum Double-Glazed 12 SF, 1-2 Stories, Replace		30	15	15	139	EA	\$584.21	\$671.84	\$93,385																						\$93,385		
B20	Throughout	880755	Window, Aluminum Double-Glazed 24 SF, 1-2 Stories, Replace		30	15	15	96	EA	\$870.45	\$1,001.02	\$96,098																						\$96,098		
B20	Throughout	880752	Exterior Door, Steel w/ Safety Glass, Replace		25	13	12	27	EA	\$1,352.72	\$1,555.63	\$42,002																						\$42,002		
B20	multipurpose room	880751	Exterior Door, Steel Insulated, Replace		25	13	12	1	EA	\$1,577.53	\$1,814.16	\$1,814																						\$1,814		
B20	Main roof	881331	Roof, Single-Ply TPO/PVC Membrane, Replace		20	10	10	57200	SF	\$15.93	\$18.32	\$1,047,935																						\$1,047,935		
B20	Main roof	881341	Roof Skylight, Plexiglass Dome Fixed 9-20 SF, Replace		30	16	14	2	EA	\$1,207.20	\$1,388.27	\$2,777																						\$2,777		
C10	106/107	881103	Wall Partitions, Movable/Hinged/Folding, Acoustical Dampening, Replace		25	21	4	10	LF	\$25.00	\$25.00	\$250											\$250											\$250		
C10	109/108	881243	Wall Partitions, Movable/Hinged/Folding, Acoustical Dampening, Replace		25	21	4	10	LF	\$25.00	\$25.00	\$250											\$250											\$250		
C10	302	880789	Wall Partitions, Movable/Hinged/Folding, Acoustical Dampening, Replace		25	13	12	20	LF	\$245.58	\$282.42	\$5,648																						\$5,648		
C10	202/203	880770	Wall Partitions, Movable/Hinged/Folding, Acoustical Dampening, Replace		25	13	12	20	LF	\$245.58	\$282.42	\$5,648																						\$5,648		
C10	210/211	880782	Wall Partitions, Movable/Hinged/Folding, Acoustical Dampening, Replace		25	13	12	20	LF	\$245.58	\$282.42	\$5,648																						\$5,648		
C10	hallways	880947	Interior Door, Fire 90-Minutes and Over, Replace		20	11	9	10	EA	\$1,649.06	\$1,896.42	\$18,964																						\$18,964		
C10	Throughout	880773	Interior Door, Steel w/ Safety Glass, Replace		20	11	9	95	EA	\$1,352.72	\$1,555.63	\$147,785																						\$147,785		
C10	Throughout	881364	Interior Door, Wood Solid-Core, Replace		20	6	14	95	EA	\$1,423.11	\$1,636.58	\$155,475																						\$155,475		
D70	Throughout	946251	Exterior Door Hardware, Electronic Door Locks ANSI F39 Lockset, Replace		30	29	1	27	EA	\$1,345.00	\$1,546.75	\$41,762	\$41,762																						\$41,762	
C10	Restroom	881336	Toilet Partitions, Metal Overhead-Braced, Replace		20	16	4	4	EA	\$850.00	\$977.50	\$3,910																						\$3,910		
C10	Mechanical room	881201	Interior Wall Finish, Gypsum Board/Plaster, Repair		0	0	0	1500	SF	\$3.18	\$3.66	\$5,488	\$5,488																						\$5,488	
C10	Throughout	881363	Interior Wall Finish, Concrete/Masonry, Prep & Paint		8	6	2	92500	SF	\$1.45	\$1.67	\$154,350																						\$154,350		
C10	Gymnasium	880926	Interior Wall Finish, Acoustical Tile (ACT), Replace		10	6	4	2000	SF	\$7.57	\$8.71	\$17,411																						\$17,411		
C10	multipurpose rm	881362	Interior Floor Finish, Maple Sports Floor, Refinish		10	4	6	2000	SF	\$4.53	\$5.21	\$10,428																						\$10,428		
C10	Throughout	880767	Interior Floor Finish, Vinyl Tile (VCT), Replace		15	9	6	34040	SF	\$4.80	\$5.52	\$187,924																						\$187,924		
C10	media & offices	881108	Interior Floor Finish, Carpet Tile Commercial-Grade, Replace		10	5	5	8000	SF	\$6.96	\$8.01	\$64,059																						\$64,059		
C10	301	880799	Interior Ceiling Finish, Gypsum Board/Plaster, Prep & Paint		10	6	4	2000	SF	\$1.94	\$2.23	\$4,454																						\$4,454		
C10	Classroom	880964	Interior Ceiling Finish, Acoustical Tile (ACT) Dropped Fiberglass, Replace		20	18	2	10000	SF	\$5.05	\$10.85	\$108,528																						\$108,528		
C10	hallways	880956	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace		20	11	9	15000	SF	\$3.11	\$3.58	\$53,665																						\$53,665		
C10	Throughout	881365	Interior Ceiling Finish, Acoustical Tile (ACT) Dropped Fiberglass, Replace		20	1	19	10000	SF	\$5.05	\$5.80	\$58,050																						\$58,050		
D20	Restroom	880763	Toilet, Tankless (Water Closet), Replace		20	11	9	14	EA	\$842.97	\$969.41	\$13,572																						\$13,572		
D20	Restroom	881337	Urinal, Vitreous China, Replace		20	11	9	2	EA	\$1,193.44	\$1,372.46	\$2,745																						\$2,745		
D20	Kitchen	881218	Sink, Trough Style, Solid Surface, Replace		20	11	9	1	EA	\$2,332.00	\$2,681.80	\$2,682																						\$2,682		
D20	Throughout	881338	Sink, Stainless Steel, Replace		20	11	9	28	EA	\$1,054.05	\$1,212.16	\$33,940																						\$33,940		
D20	Restroom	880764	Sink, Vitreous China, Replace		20	11	9	14	EA	\$861.51	\$990.74	\$13,870																						\$13,870		
D20	315	880838	Drinking Fountain, Refrigerated, Replace		10	10																														

EMG Renamed Item Number	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	w/ Markup *	Subtotal	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037RRR	RowGrandTotalLabel						
D30	Main roof	881287	Split System HVAC, Interior & Exterior Component Pairing, 3.5 Ton, Replace	15	2	13	1	EA	\$7,200.00	\$8,280.00	\$8,280																						\$8,280	\$8,280				
D30	Main roof	881315	Air Handler, Exterior, 3,001 to 4,000 CFM, Replace	15	11	4	1	EA	\$19,738.18	\$22,698.91	\$22,699						\$22,699																	\$22,699	\$45,398			
D30	computer lab	880843	Fan Coil Unit, 3 Ton, Replace	15	8	7	1	EA	\$3,416.79	\$3,929.31	\$3,929								\$3,929																\$3,929			
D30	204	880775	Fan Coil Unit, 1 to 1.5 Ton, Replace	15	8	7	1	EA	\$1,878.84	\$2,160.67	\$2,161								\$2,161																\$2,161			
D30	kitchen store rm	881239	Variable Air Volume (VAV) Unit, 401 to 800 CFM, Replace	15	6	9	1	EA	\$4,983.58	\$5,731.11	\$5,731										\$5,731														\$5,731			
D30	Mechanical Room AHU2	881330	Air Handler, Interior, 8,001 to 10,000 CFM, Replace	30	11	19	1	EA	\$31,181.53	\$35,858.76	\$35,859																							\$35,859	\$35,859			
D30	Mechanical Room AHU4	881317	Air Handler, Interior, 6,501 to 8,000 CFM, Replace	30	11	19	1	EA	\$26,016.62	\$29,919.11	\$29,919																								\$29,919	\$29,919		
D30	Mechanical Room AHU5	881210	Air Handler, Interior, 8,001 to 10,000 CFM, Replace	30	11	19	1	EA	\$31,181.53	\$35,858.76	\$35,859																								\$35,859	\$35,859		
D30	Mechanical Room	881192	Air Handler, Interior, 8,001 to 10,000 CFM, Replace	30	11	19	1	EA	\$31,181.53	\$35,858.76	\$35,859																								\$35,859	\$35,859		
D30	Mechanical Room AHU5	881326	Air Handler, Interior, 8,001 to 10,000 CFM, Replace	30	11	19	1	EA	\$31,181.53	\$35,858.76	\$35,859																								\$35,859	\$35,859		
D30	Mechanical Room AHU3	881329	Air Handler, Interior, 8,001 to 10,000 CFM, Replace	30	11	19	1	EA	\$31,181.53	\$35,858.76	\$35,859																								\$35,859	\$35,859		
D30	Main roof	881319	Exhaust Fan, Centrifugal, 251 to 800 CFM, Replace	15	15	0	1	EA	\$2,021.87	\$2,325.15	\$2,325	\$2,325															\$2,325								\$2,325	\$4,650		
D30	Main roof	881285	Exhaust Fan, Centrifugal, 251 to 800 CFM, Replace	15	11	4	1	EA	\$2,021.87	\$2,325.15	\$2,325						\$2,325																		\$2,325	\$4,650		
D30	Main roof	881280	Exhaust Fan, Centrifugal, 251 to 800 CFM, Replace	15	9	6	1	EA	\$2,021.87	\$2,325.15	\$2,325							\$2,325																	\$2,325	\$2,325		
D30	Main roof	881288	Exhaust Fan, Centrifugal, 251 to 800 CFM, Replace	15	9	6	1	EA	\$2,021.87	\$2,325.15	\$2,325							\$2,325																	\$2,325	\$2,325		
D30	Mechanical room AHU6	881203	Exhaust Fan, Centrifugal, 100 to 250 CFM, Replace	15	6	9	1	EA	\$889.90	\$889.90	\$890										\$890															\$890	\$890	
D30	Mechanical room AHU5	881209	Exhaust Fan, Centrifugal, 100 to 250 CFM, Replace	15	6	9	1	EA	\$889.90	\$889.90	\$890										\$890															\$890	\$890	
D30	Mechanical room AHU2	881325	Exhaust Fan, Centrifugal, 100 to 250 CFM, Replace	15	6	9	1	EA	\$889.90	\$889.90	\$890										\$890															\$890	\$890	
D30	Main roof	881328	Packaged Unit (RTU), 8 to 10 Ton, Replace	15	11	4	1	EA	\$18,554.44	\$21,337.61	\$21,338						\$21,338																		\$21,338	\$42,675		
D30	Main roof	881321	Packaged Unit (RTU), 16 to 20 Ton, Replace	15	11	4	1	EA	\$36,777.37	\$42,293.98	\$42,294							\$42,294																		\$42,294	\$84,588	
D30	Mechanical room	881114	Building Automation System (HVAC Controls), Upgrade	20	11	9	50000	SF	\$5.36	\$6.17	\$308,344										\$308,344															\$308,344		
D40	Interior	937490	Sprinkler System, Full Retrofit, School (per SF), Renovate	50	46	4	50000	SF	\$6.25	\$7.19	\$359,576						\$359,576																			\$359,576		
D50	Mechanical room	881248	Building/Main Switchgear, 208 Y, 120 V, 1,200 Amp, Replace	30	23	7	1	EA	\$212,265.31	\$244,105.10	\$244,105									\$244,105																\$244,105		
D50	210 near	880784	Distribution Panel, 208 Y, 120 V, 200 Amp, Replace	30	21	9	6	EA	\$7,906.20	\$9,092.13	\$9,092											\$9,092														\$9,092		
D50	Mechanical room	881250	Switchboard, 600 Amp, Replace	30	11	19	1	EA	\$24,768.06	\$28,483.27	\$28,483																									\$28,483	\$28,483	
D50	314	880841	Fluorescent Lighting Fixture, 80 W, Replace	20	20	0	1	EA	\$241.87	\$241.87	\$242	\$242																								\$242	\$242	
D50	Throughout	880766	Lighting System, Interior, School, Upgrade	25	22	3	50000	SF	\$15.36	\$17.67	\$883,396																									\$883,396		
D60	Front entrance	946250	Intercom Master Station, Replace	20	19	1	1	EA	\$3,814.50	\$4,386.67	\$4,387		\$4,387																						\$4,387			
D50	Throughout	945804	Clock and Bell System, Wireless or Ethernet Enabled, Up To 100 Total Clocks / Bells, Replace	15	14	1	50000	SF	\$0.51	\$0.59	\$29,325		\$29,325																						\$29,325	\$58,650		
D70	office	881247	Fire Alarm Control Panel, Addressable, Replace	15	9	6	1	EA	\$20,297.59	\$23,342.23	\$23,342								\$23,342																	\$23,342		
D70	Throughout	946252	Security/Surveillance System, Cameras and CCTV, Install	10	9	1	50000	SF	\$4.35	\$5.00	\$249,964		\$249,964										\$249,964													\$249,964		
D50	310	880818	Emergency/Exit Combo LED, Install	10	10	0	1	EA	\$687.51	\$687.51	\$688	\$688										\$688														\$688	\$1,375	
D50	Kitchen Store Rm	881241	Emergency Lighting Pack, 2 Light w/ Battery, Replace	10	8	2	1	EA	\$1,227.87	\$1,412.05	\$1,412			\$1,412											\$1,412											\$1,412	\$2,824	
C10	multi-purpose room	881235	Stage Curtain, Medium Weight Velour, Flameproof (per SF), Replace	15	9	6	2100	SF	\$13.00	\$14.95	\$31,395							\$31,395																		\$31,395		
E10	Kitchen	881228	Commercial Kitchen, Steamer, Tabletop, Replace	10	6	4	1	EA	\$6,344.00	\$7,295.60	\$7,296						\$7,296									\$7,296										\$7,296	\$14,591	
E10	Kitchen	881232	Commercial Kitchen, Convection Oven, Double, Replace	10	6	4	1	EA	\$8,643.00	\$9,939.45	\$9,939						\$9,939									\$9,939											\$9,939	\$19,879
E10	Kitchen	881233	Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	9	6	1	EA	\$4,256.00	\$4,894.40	\$4,894								\$4,894																		\$4,894	
E10	Kitchen	881230	Commercial Kitchen, Refrigerator, 1-Door Reach-In, Replace	15	9	6	1	EA	\$2,515.00	\$2,892.25	\$2,892								\$2,892																		\$2,892	
D20	313	880824	Commercial Kitchen, Exhaust Hood, Replace	15	8	7	1	EA	\$2,000.00	\$2,300.00	\$2,300								\$2,300																	\$2,300		
E10	Kitchen	881226	Commercial Kitchen, milk cooler, Replace	15	6	9	1	EA	\$2,515.00	\$2,892.25	\$2,892											\$2,892															\$2,892	
D30	Gymnasium	880935	Residential Fixtures, Ceiling Fan, Replace	15	4	11	2	EA	\$2,000.00	\$2,300.00	\$4,600													\$4,600												\$4,600		
C10	Throughout	881340	Kitchen Cabinet, Base and Wall Section, Wood, Replace	20	11	9	420	LF	\$467.63	\$537.78	\$225,867											\$225,867														\$225,867		
	Site	958707	Davis Bacon Prevailing Wages, Surcharge for Prevailing Wages, 10% surcharge for prevailing wages	1	1	0	50381.02	LS	\$1.00	\$1.15	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$57,938	\$1,158,763		
G20	Parking lot	880577	Roadways, Asphalt Pavement																																			

EMG Renamed Item Number	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	w/ Markup *	Subtotal	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	RRR_RowGrandTotalLabel							
<b>Totals, Unescalated</b>												\$649,696	\$398,960	\$425,109	\$952,828	\$570,915	\$567,040	\$327,924	\$363,054	\$57,938	\$1,123,958	\$1,262,357	\$312,606	\$169,372	\$77,713	\$525,129	\$339,445	\$465,767	\$90,692	\$212,288	\$460,539								\$9,353,331
<b>Totals, Escalated (3.0% inflation, compounded annually)</b>												\$649,696	\$410,929	\$450,998	\$1,041,181	\$642,570	\$657,355	\$391,559	\$446,511	\$73,394	\$1,466,510	\$1,696,502	\$432,720	\$241,483	\$114,124	\$794,305	\$528,844	\$747,419	\$149,900	\$361,407	\$807,557								\$12,104,965

\* Markup/LocationFactor (1) has been included in unit costs. Markup includes a and 15% Ann Arbor Premium factors applied to the location adjusted unit cost.

# TABLE OF CONTENTS

<b>1</b>	<b>Executive Summary</b> .....	<b>1</b>
1.1	Property Information and General Physical Condition .....	1
1.2	Key Findings .....	2
1.3	Facility Condition Index (FCI) .....	2
<b>2</b>	<b>Building Structure</b> .....	<b>4</b>
	A10 Foundations.....	4
	B10 Superstructure.....	4
<b>3</b>	<b>Building Envelope</b> .....	<b>6</b>
	B20 Exterior Vertical Enclosures .....	6
	B30 Roof.....	7
<b>4</b>	<b>Interiors</b> .....	<b>9</b>
	C10 Interior Construction.....	9
<b>5</b>	<b>Services (MEPF)</b> .....	<b>11</b>
	D10 Conveying Systems .....	11
	D20 Plumbing .....	11
	D30 Building Heating, Ventilating, and Air Conditioning (HVAC) .....	12
	D40 Fire Protection.....	14
	D50 Electrical.....	15
	D60 Communications .....	16
	D70 Electronic Safety and Security .....	16
<b>6</b>	<b>Equipment &amp; Furnishings</b> .....	<b>17</b>
	E10 Equipment .....	17
<b>7</b>	<b>Sitework</b> .....	<b>19</b>
	G20 Site Improvements.....	19
	G30 Liquid & Gas Site Utilities .....	22
	G40 Electrical Site Improvements .....	23
<b>8</b>	<b>Ancillary Structures</b> .....	<b>24</b>
<b>9</b>	<b>Opinions of Probable Costs</b> .....	<b>25</b>
	9.1 Methodology .....	25
	9.2 Immediate Repairs .....	25
	9.3 Replacement Reserves .....	25
<b>10</b>	<b>Purpose and Scope</b> .....	<b>26</b>
	10.1 Purpose .....	26
	10.2 Scope .....	27
<b>11</b>	<b>Accessibility and Property Research</b> .....	<b>28</b>
	11.1 ADA Accessibility.....	28
	11.2 Flood Zone and Seismic Zone .....	28
<b>12</b>	<b>Certification</b> .....	<b>29</b>
<b>13</b>	<b>Appendices</b> .....	<b>30</b>

# 1 Executive Summary

## 1.1 Property Information and General Physical Condition

The property information is summarized in the table below. More detailed descriptions may be found in the various sections of the report and in the Appendices.

Property Information	
Address:	2250 South Seventh Street, Ann Arbor, Washtenaw, MI 48103
Year Constructed/Renovated:	1961, Phase I / 1996 Phase II (estimated)
Current Occupants:	Ann Arbor Pubic Schools
Percent Utilization:	100 percent utilized to support the school.
Management Point of Contact:	Ann Arbor Pubic Schools/Physical Properties, Jim Vibbart, 734-320-3613 phone
Property Type:	Classrooms, Office, and support space
Site Area:	14.4 acres
Building Area:	50,000 SF
Number of Buildings:	1
Number of Stories:	1
Parking Type and Number of Spaces:	61 spaces in open lot
Building Construction:	Conventional wood frame structure on concrete slab/ with raised floor. Masonry bearing walls and wood-framed roofs. Steel frame with concrete-topped metal decks. Concrete tilt-up bearing walls and wood panel roof.
Roof Construction:	Hexagonal Gazebo and flat roofs with TPO single ply membrane.
Exterior Finishes:	Brick Veneer
Heating, Ventilation & Air Conditioning:	The building heating is primarily completed with Air handlers with heating sections. There are selective areas with cooling with is done either with a roof-top condenser for ductless systems or with a Package Unit. The rooms are supplied with air via underfloor duck work.
Fire and Life/Safety:	Hydrants, smoke detectors, alarms, strobes, extinguishers, pull stations, alarm panel, and exit signs.
ADA:	This building does not have any major ADA issues
All 50,000 square feet of the building are occupied by a single occupant, Ann Arbor Public Schools. The space is a combination of offices, classrooms, and supporting utility spaces.	
A most representative sample of the interior spaces were observed to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, exterior of the property and the roof. All areas of the property were available for observation during the site visit.	
Assessment Information	
Dates of Visit:	March 9, 2018
On-Site Point of Contact (POC):	Jim Vibbart
Assessment and Report Prepared by:	Randall Patzke

Property Information	
Reviewed by:	Al Diefert Technical Report Reviewer For Andrew Hupp Program Manager <a href="mailto:ahupp@emgcorp.com">ahupp@emgcorp.com</a> 800.733.0660 x6632

## 1.2 Key Findings

**Site:** The sidewalk between the parking lot and the fence is heaved and retains water that can freeze. The paving parking lot, playground and sidewalk need seal coating with restriping. The facility has a pest control issue related to ants.


**Architectural:** The exterior walls at the corners of the hexagonal walls have multiple issues related to the brick work. This includes brick failure, re-pointing of brick joints and the actual caulking. The mechanical penthouses have not been repaired after the installation of the new air handlers.

**MEPF:** The air handlers in the mechanical rooms do not have a cross over. To access equipment person must crawl across top of air handler. Exterior insulations are not being maintained.

## 1.3 Facility Condition Index (FCI)

### FCI Analysis: Lawton Elementary School

Replacement Value: \$ 10,000,000; Inflation rate: 3.0%



One of the major goals of the FCA is to calculate the FCI, which gives an indication of a building's overall condition. Two FCI ratios are calculated and presented, the Current Year and Ten-Year. The Current Year FCI is the ratio of Immediate Repair Costs to the building's Current Replacement Value. Similarly, the Ten-Year FCI is the ratio of anticipated Capital Reserve Needs over the next ten years to the Current Replacement Value.

Fci Condition Rating	Definition	Percentage Value
Good	In new or well-maintained condition, with no visual evidence of wear, soiling or other deficiencies.	0 to .05

Fci Condition Rating	Definition	Percentage Value
Fair	Subjected to wear and soiling but is still in a serviceable and functioning condition.	> than .05 to .10
Poor	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.	> than .10 to .60
Very Poor	Has reached the end of its useful or serviceable life. Renewal is now necessary.	> than .60

The graphs above and tables below represent summary-level findings for the FCA. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall strategy that can serve as the basis for a portfolio-wide capital improvement funding strategy. Key findings from the assessment include:

KEY FINDING	METRIC
Current Year Facility Condition Index (FCI) $FCI = (IR)/(CRV)$ :	5.15%
Current Year FCI Rating:	2018
10-Year Facility Condition Index (FCI) $FCI = (RR)/(CRV)$ :	29.06%
10-Year FCI Rating:	0.29
Current Replacement Value (CRV):	\$10,000,000
Year 0 (Current Year) - Immediate Repairs (IR):	\$514,801
Years 1-10 - Replacement Reserves (RR):	\$2,390,997
Total Capital Needs:	\$2,905,798

Further detail on the specific costs that make up the Immediate Repair Costs can be found in the cost tables at the beginning of this report.

## 2 Building Structure

### A10 Foundations

Building Foundation		
Item	Description	Condition
Foundation	Concrete spread footings	Fair
Basement and Crawl Space	None	--

#### Anticipated Lifecycle Replacements

- No components of significance

#### Actions/Comments:

- The foundation systems are concealed. There are no significant signs of settlement, deflection, or movement.

### B10 Superstructure

B1010 Floor Construction & B1020 Roof Construction		
Item	Description	Condition
Framing / Load-Bearing Walls	Masonry walls	Fair
Ground Floor	Concrete slab	Fair
Upper Floor Framing	None	--
Upper Floor Decking	None	--
Balcony Framing	None	--
Balcony Decking	None	--
Balcony Deck Toppings	None	--
Balcony Guardrails	None	--
Roof Framing	Heavy lumber beams	Fair
Roof Decking	2 x lumber	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Caulk minor cracking	<input type="checkbox"/>	Monitor cracking for growth	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

#### Anticipated Lifecycle Replacements:

- No components of significance

**Actions/Comments:**

- The superstructure is concealed. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

B1080 Stairs					
Type	Description	Riser	Handrail	Balusters	Condition
Building Exterior Stairs	Concrete stairs	Closed	Metal	None	Fair
Building Interior Stairs	Wood-framed	Closed	None	None	Fair

**Anticipated Lifecycle Replacements:**

- Refinish metal handrails

**Actions/Comments:**

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

### 3 Building Envelope

#### B20 Exterior Vertical Enclosures

B2010 Exterior Walls		
Type	Location	Condition
Primary Finish	Brick veneer	Poor
Secondary Finish	NA	--
Accented with	Metal siding	Fair
Soffits	Concealed	Fair
Building sealants	Between dissimilar materials, at joints, around windows and doors	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Graffiti	<input type="checkbox"/>	Efflorescence	<input checked="" type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

#### Anticipated Lifecycle Replacements:

- Exterior paint
- Metal Trim (siding)
- Brick veneer
- Wood trim
- Caulking
- Masonry re-pointing
- Masonry Brick Replacement

#### Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance, including patching repairs, graffiti removal, and re-caulking, is highly recommended. Future lifecycle replacements of the components listed above will be required.
- Building has an issue with ants inside the facility. This is most noticed in the 5th grade class rooms.
- The wood soffit around 314/315 has come loose and may require replacement and painting. The cost of this work is relatively insignificant and the work can be performed as part of the property management's routine maintenance program
- The metal siding below fascia has significant areas that require repainting.
- Isolated portions of the mortar joints along the brick veneer are cracked (at the non-ninety degree corners). The damaged mortar joints must be cleaned and re-pointed.
- The brick masonry has isolated areas of efflorescence (near Multi-Purpose Room entry stairs). The affected areas of brick masonry must be cleaned, and the brick sealed.
- The brick veneer has significant areas of loose units and deteriorated mortar joints (at the non-ninety-degree corners). The damaged veneer must be repaired and/or replaced.

B2020 Exterior Windows				
Window Framing	Glazing	Location	Window Screen	Condition
Aluminum framed, fixed	Double glaze	Throughout	<input type="checkbox"/>	Fair
Aluminum framed, operable	Double glaze	Throughout	<input checked="" type="checkbox"/>	Fair

B2050 Exterior Doors		
Main Entrance Doors	Door Type	Condition
	Fully glazed, metal framed	Fair
Secondary Entrance Doors	Fully glazed, metal framed	Fair
Service Doors	Metal, hollow	Fair
Overhead Doors	None	--

**Anticipated Lifecycle Replacements:**

- Windows
- Exterior doors
- Window sealants

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.
- The function of the windows should be tested and confirmed functional for Active Shooter. This should include the windows, screens and blinds. Replacing missing/damaged blinds.
- There are a few damaged, rusted doors and door frames. That require repainting and repair.

**B30 Roof**

B3010 Primary Roof			
Location	Main Roof	Finish	Single-ply membrane
Type / Geometry	Hexagonal Gazebo	Roof Age	10 Yrs
Flashing	Membrane	Warranties	Unknown
Parapet Copings	None	Roof Drains	Gutters and downspouts
Fascia	Metal Panel	Insulation	Rigid Board
Soffits	Concealed Soffits	Skylights	Yes
Attics	Concrete-topped steel decks	Ventilation Source-1	None
Roof Condition	Fair	Ventilation Source-2	--

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Drainage components broken/missing	<input type="checkbox"/>	Vegetation/fungal growth	<input type="checkbox"/>
Blocked Drains	<input type="checkbox"/>	Debris	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Evidence of roof leaks	<input type="checkbox"/>	Significant ponding	<input type="checkbox"/>
Excessive patching or repairs	<input type="checkbox"/>	Blistering or ridging	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Anticipated Lifecycle Replacements:**

- TPO roof membrane
- Roof flashings (included as part of overall membrane replacement)
- Skylights

**Actions/Comments:**

- The roof finishes appear to be more than 10 years old. Information regarding roof warranties or bonds was not available. A copy of the warranty was requested but was not available. The roofs are maintained by an outside contractor.
- According to the Principal, there are active roof leaks. There is evidence of active roof leaks. The locations were not identified. But, these leaks should be addressed and repaired.
- There is no evidence of roof deck or insulation deterioration. The roof substrate and insulation should be inspected during any future roof repair or replacement work.
- Roof drainage appears to be adequate. Clearing and minor repair of drain system components should be performed regularly as part of routine maintenance and operations program.
- The attics are not accessible, and it could not be determined if there is moisture, water intrusion, or excessive daylight in the attics.

## 4 Interiors

### C10 Interior Construction

C1030 Interior Doors		
Item	Type	Condition
Interior Doors	Solid Core Wood	Fair
Door Framing	Metal	Fair
Fire Doors	Yes	Fair
Closet Doors	Solid core wood	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Improperly adjusted door closures	<input checked="" type="checkbox"/>	Damaged/loose door hardware	<input checked="" type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

The following table generally describes the locations and typical conditions of the interior finishes within the facility:

#### Interior Finishes - LAWTON ELEMENTARY

Location	Finish		Quantity (SF)	Condition	Action	RUL	Est. Cost
Classroom	Ceiling	Gypsum Board/Plaster	2000	Fair	Prep & Paint	4	3,873
Classroom	Ceiling	Acoustical Tile (ACT) Dropped Fiberglass	10000	Fair	Replace	2	100,956
Gymnasium	Wall	Acoustical Tile (ACT)	2000	Fair	Replace	4	15,140
Hallways	Ceiling	Acoustical Tile (ACT) Dropped Fiberglass	15000	Fair	Replace	9	46,665
Mechanical room	Wall	Gypsum Board/Plaster	1500	Poor	Repair	0	4,772
Media & offices	Floor	Carpet Tile Commercial-Grade	8000	Fair	Replace	5	55,703
Multipurpose rm	Floor	Maple Sports Floor	2000	Fair	Refinish	6	9,068
Restroom	Floor	Ceramic Tile	960	Fair	Replace	37	15,125
Throughout	Ceiling	Acoustical Tile (ACT) Dropped Fiberglass	10000	NA	Replace	19	50,478
Throughout	Wall	Concrete/Masonry	60500	Fair	Prep & Paint	2	87,786
Throughout	Floor	Vinyl Tile (VCT)	34040	Fair	Replace	6	163,412

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Loose carpeting/flooring	<input type="checkbox"/>	Minor areas of stained ceiling tiles	<input checked="" type="checkbox"/>
Minor paint touch-up	<input checked="" type="checkbox"/>	Areas of damaged/missing baseboard	<input checked="" type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Anticipated Lifecycle Replacements:**

- Carpet
- Vinyl tile
- Ceramic tile
- Interior paint
- Suspended acoustic ceiling tile
- Hard tile ceilings
- Interior doors

**Actions/Comments:**

- It appears that the interior finishes have not been renovated within the last 7 years.
- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.
- The carpet to tile transition strip is missing at the entrance door to the office/hallway. These should be replaced with then finishes are updated or by maintenance as part of routine maintenance.
- The interior finishes are worn and dated. The interior of the school should be repainted.
- The ceilings in the classrooms may contain asbestos materials. If that is the case the tiles should be removed and replaced with a new acoustical dampening panel.

## 5 Services (MEPF)

### D10 Conveying Systems

Not applicable. There are no elevators or conveying systems.

### D20 Plumbing

D2010 Domestic Water Distribution		
Type	Description	Condition
Water Supply Piping	Copper	Fair
Water Meter Location	Mechanical Room	

Domestic Water Heaters or Boilers	
Components	Water Heaters
Fuel	Natural gas
Boiler or Water Heater Condition	Fair
Supplementary Storage Tanks?	No
Adequacy of Hot Water	Adequate
Adequacy of Water Pressure	Adequate

D2020 Sanitary Drainage		
Type	Description	Condition
Waste/Sewer Piping	Cast iron	Fair
Vent Piping	Cast iron	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Hot water temperature too hot or cold	<input type="checkbox"/>	Minor or isolated leaks	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Plumbing Systems - LAWTON ELEMENTARY**

Location	Component	Component Description	Quantity	Unit	Condition	RUL	Est. Cost
315	Drinking Fountain	Refrigerated	1	EA	NA	0	1,258
Gymnasium & Hallway	Drinking Fountain	Vitreous China	2	EA	Fair	6	3,878
Hallway	Drinking Fountain	Refrigerated	2	EA	Fair	4	2,515
Kitchen	Sink	Trough Style, Solid Surface	1	EA	Fair	9	2,332
Mechanical room	Water Heater	Gas, Commercial, 60 to 120 GAL	1	EA	Fair	7	10,699
Mechanical room	Water Heater	Gas, Commercial, 60 to 120 GAL	1	EA	Fair	5	10,699
Restroom	Toilet	Tankless (Water Closet)	14	EA	Fair	9	11,802
Restroom	Urinal	Vitreous China	2	EA	Fair	9	2,387
Restroom	Sink	Vitreous China	14	EA	Fair	9	12,061
Throughout	Sink	Stainless Steel	28	EA	Fair	9	29,513

**Anticipated Lifecycle Replacements:**

- Circulation pumps
- Water heaters
- Toilets
- Urinals
- Sinks

**Actions/Comments:**

- The plumbing systems appear to be well maintained and functioning adequately. The water pressure appears to be sufficient. No significant repair actions or short-term replacement costs are required. Routine and periodic maintenance is recommended. Future lifecycle replacements of the components or systems listed above will be required.

**D30 Building Heating, Ventilating, and Air Conditioning (HVAC)**

Packaged, Split & Individual Units	
Primary Components	Package units
Cooling (if separate from above)	performed via components above
Heating Fuel	Natural gas
Location of Equipment	Rooftop
Space Served by System	Entire building

Supplemental/Secondary Components	
Supplemental Component	Ductless mini-split systems
Location / Space Served	Computer rooms
Condition	Excellent

Controls and Ventilation	
HVAC Control System	BAS, direct digital controls (DDC)
HVAC Control System Condition	Fair
Building Ventilation	Central AHU, with fresh air intake
Ventilation System Condition	Good

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Ductwork/grills need cleaned	<input type="checkbox"/>	Minor control adjustments needed	<input type="checkbox"/>
Leaking condensate lines	<input type="checkbox"/>	Poor mechanical area access	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Heating, Cooling or Ventilation is not adequate	<input checked="" type="checkbox"/>	Major system inefficiencies	<input type="checkbox"/>
HVAC controls pneumatic or antiquated	<input type="checkbox"/>	Obsolete refrigerants: R11, R12, R22, R123, R502	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

## Mechanical Systems - LAWTON ELEMENTARY

Location	Component	Component Description	Quantity	Unit	Condition	Action	RUL	Est. Cost
204	Fan Coil Unit	1 to 1.5 Ton	1	EA	Fair	Replace	7	1,879
computer lab	Fan Coil Unit	3 Ton	1	EA	Excellent	Replace	7	3,417
kitchen store rm	Variable Air Volume (VAV) Unit	401 to 800 CFM	1	EA	Fair	Replace	9	4,984
Main roof	Split System HVAC	Interior & Exterior Component Pairing, 3.5 Ton	1	EA	Excellent	Replace	13	7,200
Main roof	Exhaust Fan	Centrifugal, 251 to 800 CFM	1	EA	Fair	Replace	6	2,022
Main roof	Condensing Unit	Air-Cooled, 10 Ton	1	EA	Fair	Replace	4	5,616
Main roof	Exhaust Fan	Centrifugal, 251 to 800 CFM	1	EA	Poor	Replace	0	2,022
Main roof	Exhaust Fan	Centrifugal, 251 to 800 CFM	1	EA	Fair	Replace	6	2,022
Main roof	Ductless Split System	Single Zone, 2.5 to 3 Ton	1	EA	Fair	Replace	7	6,577
Main roof	Exhaust Fan	Centrifugal, 251 to 800 CFM	1	EA	Fair	Replace	4	2,022
Main roof	Packaged Unit (RTU)	16 to 20 Ton	1	EA	Fair	Replace	4	36,777
Main roof	Air Handler	Exterior, 3,001 to 4,000 CFM	1	EA	Fair	Replace	4	19,738
Main roof	Packaged Unit (RTU)	8 to 10 Ton	1	EA	Fair	Replace	4	18,554
Mechanical room	Building Automation System (HVAC Controls)	Full Upgrade (per SF)	50000	SF	Fair	Upgrade	9	268,125
Mechanical Room	Air Handler	Interior, 8,001 to 10,000 CFM	1	EA	Good	Replace	19	31,182
Mechanical Room	Air Handler	Interior, 8,001 to 10,000 CFM	1	EA	Good	Replace	19	31,182
Mechanical Room	Air Handler	Interior, 6,501 to 8,000 CFM	1	EA	Good	Replace	19	26,017
Mechanical Room	Exhaust Fan	Centrifugal, 100 to 250 CFM	1	EA	Fair	Replace	9	890
Mechanical Room	Exhaust Fan	Centrifugal, 100 to 250 CFM	1	EA	Fair	Replace	9	890
Mechanical Room	Exhaust Fan	Centrifugal, 100 to 250 CFM	1	EA	Fair	Replace	9	890
Mechanical Room	Air Handler	Interior, 8,001 to 10,000 CFM	1	EA	Good	Replace	19	31,182
Mechanical Room	Air Handler	Interior, 8,001 to 10,000 CFM	1	EA	Good	Replace	19	31,182
Mechanical Room	Air Handler	Interior, 8,001 to 10,000 CFM	1	EA	Good	Replace	19	31,182

**Anticipated Lifecycle Replacements:**

- Air handling units
- Package units
- Condensing units
- Split system units
- Rooftop exhaust fans

**Actions/Comments:**

- The HVAC systems are maintained by an outside contractor. Records of the installation, maintenance, upgrades, and replacement of the HVAC equipment at the property have not been maintained since the property was first occupied.
- Approximately 5 percent of the HVAC equipment is original. The HVAC equipment varies in age.
- The HVAC equipment appears to be functioning adequately overall. The principal commented that the temperature control in the classrooms is an on-going issue.

**D40 Fire Protection**

Item	Description					
Type	None					
Sprinkler System	None	<input checked="" type="checkbox"/>	Standpipes	<input type="checkbox"/>	Backflow Preventer	<input type="checkbox"/>
	Hose Cabinets	<input type="checkbox"/>	Fire Pumps	<input type="checkbox"/>	Siamese Connections	<input type="checkbox"/>
Sprinkler System Condition	--					
Fire Extinguishers	Last Service Date			Servicing Current?		
	August 2017			Yes		
Hydrant Location	Front entrance					
Siamese Location	None					
Special Systems	Kitchen Suppression System		<input type="checkbox"/>	Computer Room Suppression System		<input type="checkbox"/>

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Extinguisher tag expired	<input checked="" type="checkbox"/>	Riser tag expired (5 year)	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Anticipated Lifecycle Replacements:**

- No components of significance

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

- The building is not protected by fire suppression. Due to its construction date, the facility is most likely “grandfathered” by code and the installation of fire sprinklers not required until major renovations are performed. A budgetary cost is included.
- The Fire Extinguisher contractor missed some of the extinguishers not out in the open areas.

## D50 Electrical

Distribution & Lighting			
Electrical Lines	Underground	Transformer	Pad-mounted
Main Service Size	1200 Amps	Volts	120/208 Volt, three-phase
Meter & Panel Location	Mechanical Room	Branch Wiring	Copper
Conduit	Metallic	Step-Down Transformers?	No
Security / Surveillance System?	Yes	Building Intercom System?	Yes
Lighting Fixtures	T-8, CFL		
Main Distribution Condition	Fair		
Secondary Panel and Transformer Condition	Fair		
Lighting Condition	Fair		

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Improperly stored material	<input checked="" type="checkbox"/>	Unsecured high voltage area	<input type="checkbox"/>
Loose cables or improper use of conduit	<input type="checkbox"/>	Poor electrical room ventilation	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

### **Anticipated Lifecycle Replacements:**

- Circuit breaker panels
- Main switchgear
- Switchboards
- Interior light fixtures

### **Actions/Comments:**

- The onsite electrical systems up to the meter are owned and maintained by the respective utility company.
- The electrical service and capacity appear to be adequate for the property's demands.
- The distribution panels are original 1961 components. The electrical service appears to be adequate for the facility's needs. However, due to the age of the distribution panels and increasing difficulty of obtaining replacement parts over time, lifecycle replacements are recommended.

## D60 Communications

D6060 Public Address Systems						
Item	Description					
Communication Equipment	Public Address System	<input checked="" type="checkbox"/>	Nurse Call System	<input type="checkbox"/>	Clock	<input checked="" type="checkbox"/>

## D70 Electronic Safety and Security

D7010 Access Control and Intrusion Detection / D7050 Detection and Alarm						
Item	Description					
Access Control and Intrusion Detection	Exterior Camera	<input checked="" type="checkbox"/>	Interior Camera	<input checked="" type="checkbox"/>	Front Door Camera Only	<input type="checkbox"/>
	Cameras monitored	<input type="checkbox"/>	Security Personnel On-Site	<input type="checkbox"/>	Intercom/Door Buzzer	<input checked="" type="checkbox"/>
Fire Alarm System	Central Alarm Panel	<input checked="" type="checkbox"/>	Battery-Operated Smoke Detectors	<input type="checkbox"/>	Alarm Horns	<input checked="" type="checkbox"/>
	Annunciator Panels	<input type="checkbox"/>	Hard-Wired Smoke Detectors	<input checked="" type="checkbox"/>	Strobe Light Alarms	<input checked="" type="checkbox"/>
	Pull Stations	<input checked="" type="checkbox"/>	Emergency Battery-Pack Lighting	<input checked="" type="checkbox"/>	Illuminated EXIT Signs	<input checked="" type="checkbox"/>
Fire Alarm System Condition	Good					
Central Alarm Panel System	Location of Alarm Panel		Installation Date of Alarm Panel			
	Office		2016			

**Anticipated Lifecycle Replacements:**

- Fire alarm panel
- Emergency lighting

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

## 6 Equipment & Furnishings

### E10 Equipment

The kitchen includes the following major appliances, fixtures, and equipment:

E1030 Commercial Kitchen Equipment		
Appliance	Comment	Condition
Refrigerators	Up-right	Fair
Freezers	<input type="checkbox"/>	--
Ranges	<input type="checkbox"/>	--
Ovens	Electric	Fair
Griddles / Grills	<input type="checkbox"/>	--
Fryers	<input type="checkbox"/>	--
Hood	Exhaust ducted to exterior	Fair
Dishwasher	<input type="checkbox"/>	--
Microwave	<input type="checkbox"/>	--
Ice Machines	<input type="checkbox"/>	--
Steam Tables	<input checked="" type="checkbox"/>	Fair
Work Tables	<input checked="" type="checkbox"/>	Fair
Shelving	<input type="checkbox"/>	--

E1030 Commercial Laundry		
Equipment	Comment	Condition
Commercial Washing Machines	<input type="checkbox"/>	--
Commercial Dryers	<input type="checkbox"/>	--
Residential Washers	<input type="checkbox"/>	--
Residential Dryers	<input type="checkbox"/>	--

#### **Anticipated Lifecycle Replacements:**

- Convection warming oven
- Reach-in refrigerator
- Milk coolers
- Oven Hood
- Steam table

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

## 7 Sitework

### G20 Site Improvements

G2020 Parking Lots & G2030 Pedestrian Walkways		
Item	Material	Condition
Entrance Driveway Apron	Asphalt	Fair
Parking Lot	Asphalt	Fair
Drive Aisles	Asphalt	Fair
Service Aisles	Asphalt	Fair
Sidewalks	Concrete	Fair
Curbs	Concrete	Fair
Pedestrian Ramps	--	--
Ground Floor Patio or Terrace	--	--

Parking Count				
Open Lot	Carport	Private Garage	Subterranean Garage	Freestanding Parking Structure
58	-	-	-	-
Total Number of ADA Compliant Spaces			2	
Number of ADA Compliant Spaces for Vans			1	
Total Parking Spaces			61	

Site Stairs			
Location	Material	Handrails	Condition
Multi-Purpose Entry	Concrete stairs	Metal	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Pavement oil stains	<input type="checkbox"/>	Vegetation growth in joints	<input type="checkbox"/>
Stair/ramp rails loose	<input type="checkbox"/>	Stair/ramp rail needs scraped and painted	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Potholes/depressions	<input type="checkbox"/>	Alligator cracking	<input type="checkbox"/>
Concrete spalling	<input type="checkbox"/>	Trip hazards (settlement/heaving)	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Anticipated Lifecycle Replacements:**

- Asphalt seal coating
- Asphalt pavement
- Sidewalks

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.
- The concrete sidewalks have isolated areas of vertically-displaced concrete due to mature tree root growth and settlement. These areas occur (between the fence and parking lot). The damaged areas of concrete sidewalks require replacement.

G2060 Site Development	
Property Signage	
Property Signage	Monument
Street Address Displayed?	Yes

Site Fencing		
Type	Location	Condition
Stained wood board and posts	Entry	Fair
Chain link with metal posts	Part of playground	Fair

Refuse Disposal				
Refuse Disposal	Common area dumpsters			
Dumpster Locations	Mounting	Enclosure	Contracted?	Condition
Front entry	Concrete pad	None	Yes	Fair

Other Site Amenities			
	Description	Location	Condition
Playground Equipment	Plastic and metal	Playground	Fair
Tennis Courts	None	--	--

Other Site Amenities			
	Description	Location	Condition
Basketball Court	Asphalt	Playground	Fair
Swimming Pool	None	--	--

**Anticipated Lifecycle Replacements:**

- Signage
- Site fencing
- Playground equipment
- Playground surfaces
- Asphalt paving (walkways and parking lot)

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

G2080 Landscaping		
Drainage System and Erosion Control		
System	Exists At Site	Condition
Surface Flow	<input checked="" type="checkbox"/>	Fair
Inlets	<input checked="" type="checkbox"/>	Fair
Swales	<input type="checkbox"/>	--
Detention pond	<input type="checkbox"/>	--
Lagoons	<input type="checkbox"/>	--
Ponds	<input type="checkbox"/>	--
Underground Piping	<input checked="" type="checkbox"/>	Fair
Pits	<input type="checkbox"/>	--
Municipal System	<input checked="" type="checkbox"/>	Fair
Dry Well	<input type="checkbox"/>	--

**Anticipated Lifecycle Replacements:**

- No components of significance

**Actions/Comments:**

- There is evidence of storm water runoff from adjacent properties. The storm water system appears to provide adequate runoff capacity. There is no evidence of major ponding or erosion. But, the principal did comment that water can be an issue on the site.

Item	Description
Site Topography	The site is relatively flat. There is a slope from the Southeast corner of the site to the building.

Item	Description						
Landscaping	Trees	Grass	Flower Beds	Planters	Drought Tolerant Plants	Decorative Stone	None
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>				
Landscaping Condition	Fair						
Irrigation	Automatic Underground		Drip		Hand Watering		None
	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input checked="" type="checkbox"/>
Irrigation Condition	--						

Retaining Walls		
Type	Location	Condition
None	--	--

**Anticipated Lifecycle Replacements:**

- Landscaping materials

**Actions/Comments:**

- The topography and adjacent uses do not appear to present conditions detrimental to the property. There are no significant areas of erosion.

**G30 Liquid & Gas Site Utilities**

G3060 Site Fuel Distribution	
Item	Description
Natural Gas	Gas service is supplied from the gas main on the adjacent public street. The gas meter and regulator are located along the exterior walls of the building. The gas distribution piping within the building is malleable steel (black iron).

**Anticipated Lifecycle Replacements:**

- No components of significance

**Actions/Comments:**

- The pressure and quantity of gas appear to be adequate.
- The gas meter and regulator appear to be functioning adequately and will require routine maintenance.
- Only limited observation of the gas distribution piping can be made due to hidden conditions.

## G40 Electrical Site Improvements

G4050 Site Lighting					
Site Lighting	None	Pole Mounted	Bollard Lights	Ground Mounted	Parking Lot Pole Type
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Fair				
Building Lighting	None		Wall Mounted	Recessed Soffit	
	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	Excellent				

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Isolated bulb/lamp replacement	<input type="checkbox"/>	Discolored/dirty lens cover	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

**Anticipated Lifecycle Replacements:**

- Exterior lighting

**Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

## 8 Ancillary Structures

Other Ancillary Structures			
Type	Maintenance/Storage Shed	Location	Site
Item	Material	Item	Material
Exterior Siding	Pre-Cast Concrete	Roof Finishes	Pre-cast concrete
Interior Finishes	Floor: Exposed concrete Ceiling: Exposed concrete Walls: Exposed concrete (based on Transportation bldg.)	MEPF	Electrical (was not able to access)
Overall Building Condition			Fair
Type	Storage Shed	Location	Garden
Item	Material	Item	Material
Exterior Siding	Wood	Roof Finishes	Asphalt Singles
Interior Finishes	Floor: Wood Ceiling: Exposed Walls: Wood	MEPF	None
Overall Building Condition			Fair

### **Anticipated Lifecycle Replacements:**

- No components of significance

### **Actions/Comments:**

- No significant actions are identified now. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

## 9 Opinions of Probable Costs

---

Cost estimates are attached at the front of this report (following the cover page).

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means* and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc. ASTM E2018-08 recognizes that certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

### 9.1 Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age. Projections of Remaining Useful Life (RUL) are based on continued use of the Property similar to the reported past use. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be derived from an actual take-off, lump sum costs or allowances are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

### 9.2 Immediate Repairs

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) material building or fire code violations, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

### 9.3 Replacement Reserves

Replacement Reserves are for recurring probable expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Repair Cost Estimate

## 10 Purpose and Scope

### 10.1 Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record at municipal offices, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

#### CONDITIONS:

The physical condition of building systems and related components are typically defined as being in one of five conditions: Excellent, Good, Fair, Poor, Failed or a combination thereof. For the purposes of this report, the following definitions are used:

Excellent	=	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	=	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	=	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	=	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	=	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	=	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Throughout sections 5 through 9 of this report, each report section will typically contain three subsections organized in the following sequence:

- A descriptive table (and/or narrative), which identifies the components assessed, their condition, and other key data points.
- A simple bulleted list of Anticipated Lifecycle Replacements, which lists components and assets typically in Excellent, Good, or Fair condition at the time of the assessment but that will require replacement or some other attention once aged past their estimated useful life. These listed components are typically included in the associated inventory database with costs identified and budgeted beyond the first several years.
- A bulleted cluster of Actions/Comments, which include more detailed narratives describing deficiencies, recommended repairs, and short term replacements. The assets and components associated with these bullets are/were typically problematic and in Poor or Failed condition at the time of the assessment, with corresponding costs included within the first few years.

**PLAN TYPES:**

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance. The following Plan Types are listed in general weighted order of importance:

Safety	=	An observed or reported unsafe condition that if left unaddressed could result in an injury; a system or component that presents a potential liability risk.
Performance/Integrity	=	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses a risk to overall system stability.
Accessibility	=	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	=	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Modernization/Adaptation	=	Conditions, systems, or spaces that need to be upgraded in appearance or function to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	=	Any component or system in which future repair or replacement is anticipated beyond the next several years and/or is of minimal substantial early-term consequence.

## 10.2 Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a general statement of the subject Property’s compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Perform a limited assessment of accessible areas of the building(s) for the presence of fungal growth, conditions conducive to fungal growth, and/or evidence of moisture. EMG will also interview Project personnel regarding the presence of any known or suspected fungal growth, elevated relative humidity, water intrusion, or mildew-like odors. Potentially affected areas will be photographed. Sampling will not be considered in routine assessments.
- List the current utility service providers.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, in order to gain a clear understanding of the property’s overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report.
- Prepare a mechanical inventory list.

## 11 Accessibility and Property Research

### 11.1 ADA Accessibility

Generally, Title III of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of "areas of public accommodations" and "commercial facilities" on the basis of disability. Regardless of its age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

Buildings completed and occupied after January 26, 1992 are required to comply fully with the ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of compliance to the extent allowed by structural feasibility and the financial resources available. As an alternative, a reasonable accommodation pertaining to the deficiency must be made.

During the FCA, a limited visual observation for ADA accessibility compliance was conducted. The scope of the visual observation was limited to those areas set forth in *EMG's Abbreviated Accessibility Checklist* provided in Appendix D of this report. It is understood by the Client that the limited observations described herein does not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG's undertaking. Only a representative sample of areas was observed and, other than as shown on the Abbreviated Accessibility Checklist, actual measurements were not taken to verify compliance.

The facility does not appear to be accessible with Title III of the Americans with Disabilities Act. Elements as defined by the ADAAG that are not accessible as stated within the priorities of Title III, are as follows:

Accessibility Issues			
Component	Major Issue	Moderate Issue	Minor Issue
Parking	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Exterior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Interior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Restrooms	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Elevators	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

One of the parking spaces is missing the ADA Parking sign. The common area restrooms the piping beneath the sinks is not wrapped. The wrap is protecting a person's legs.

A full ADA Compliance Survey may reveal aspects of the property that are not in compliance.

Corrections of these conditions should be addressed from a liability standpoint, but are not necessarily code violations. The Americans with Disabilities Act Accessibility Guidelines concern civil rights issues as they pertain to the disabled and are not a construction code, although many local jurisdictions have adopted the Guidelines as such.

### 11.2 Flood Zone and Seismic Zone

According to the Flood Insurance Rate Map, published by the Federal Emergency Management Agency (FEMA) and dated April 3, 2012, the property is located in Zone X, defined as an area outside the 500-year flood plain with less than 0.2% annual probability of flooding. Annual Probability of Flooding of Less than one percent.

According to the 1997 Uniform Building Code Seismic Zone Map of the United States, the property is located in Seismic Zone 1, defined as an area of low probability of damaging ground motion.

## 12 Certification

---

Ann Arbor Public Schools retained EMG to perform this Facility Condition Assessment in connection with its continued operation of Lawton Elementary, 2250 South Seventh Street, Ann Arbor, MI, the "Property". It is our understanding that the primary interest of Ann Arbor Public Schools is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in depth studies were performed unless specifically required under Section 2 of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas were observed (See Section 4.2 for areas observed). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the client for the purpose stated within Section 10 of this report. The report, or any excerpt thereof, shall not be used by any party other than the client or for any other purpose than that specifically stated in our agreement or within Section 10.1 of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at Ann Arbor Public Schools and the recipient's sole risk, without liability to EMG.

**Prepared by:** Randall Patzke,  
Project Manager

**Reviewed by:**



---

Al Diefert  
Technical Report Reviewer For  
Andrew Hupp  
Program Manager

## 13 Appendices

---

- Appendix A: Photographic Record
- Appendix B: Site Plans
- Appendix C: Supporting Documentation
- Appendix D: EMG Accessibility Checklist
- Appendix E: Pre-Survey Questionnaire

---

---

## **Appendix A: Photographic Record**

---

---



#1:	FRONT ELEVATION
-----	-----------------



#2:	RIGHT ELEVATION
-----	-----------------



#3:	REAR ELEVATION
-----	----------------



#4:	LEFT ELEVATION
-----	----------------



#5:	CEILING TILE POSSIBLY CONTAINING ASBESTOS
-----	---



#6:	PIPE INSULATION WITH POSSIBLE ASBESTOS
-----	--



#7:	EXTERIOR WALL
-----	---------------



#8:	EXTERIOR DOORS, EXTERIOR FASCIA
-----	---------------------------------



#9:	EXTERIOR DOOR
-----	---------------



#10:	EXTERIOR STAIR/RAMP RAILS
------	---------------------------



#11:	MECHANICAL ROOM HATCH NEEDS PAINTING
------	--------------------------------------



#12:	ROOF MEMBRANE
------	---------------



#13:	WINDOWS
------	---------



#14:	WOOD SOFFIT
------	-------------



#15:	DAMAGED BRICK VENEER
------	----------------------



#16:	ROOF HVAC
------	-----------



#17:	BRICK VENEER
------	--------------



#18:	ROOF EXHAUST FAN
------	------------------



#19:	EXTERIOR DOOR
------	---------------



#20:	CASEWORK
------	----------



#21:	ACOUSTICAL INTERIOR WALL FINISH, WITH CEILING FAN
------	---



#22:	VINYL TILE FLOOR
------	------------------



#23:	INTERIOR CARPET
------	-----------------



#24:	WALL PARTITION
------	----------------



#25:	ACOUSTICAL INTERIOR CEILING
------	-----------------------------



#26:	CASEWORK
------	----------



#27:	INTERIOR DOOR
------	---------------



#28:	REPAIR INTERIOR WALL FINISH
------	-----------------------------



#29:	STAGE CURTAIN
------	---------------



#30:	ACOUSTICAL WALL PARTITIONS
------	----------------------------



#31:	ACOUSTICAL WALL PARTITIONS
------	----------------------------



#32:	INTERIOR CEILING TILE
------	-----------------------



#33:	REPAIR INTERIOR WALL FINISH
------	-----------------------------



#34:	CARPET
------	--------



#35:	DAMAGED CONCRETE BLOCK
------	------------------------



#36:	HARD CEILING FINISH
------	---------------------



#37:	HARDWOOD FLOORING
------	-------------------



#38:	OFFICE
------	--------



#39:	ACOUSTICAL INTERIOR WALL FINISH
------	---------------------------------



#40:	INTERIOR WALL FINISHES
------	------------------------



#41:	TOILET, SINK AND CERAMIC TILE FLOORING
------	--



#42:	TOILET PARTITIONS
------	-------------------



#43:	WOOD CABINETS
------	---------------



#44:	HALLWAY
------	---------



#45:	CLASROOM
------	----------



#46:	INTERIOR WALL AND CEILING FINISH TO REPAIR
------	--



#47:	GLAZED, STEEL INTERIOR DOOR
------	-----------------------------



#48:	ACT INTERIOR CEILING FINISH
------	-----------------------------



#49:	VINYL TILE FLOOR
------	------------------



#50:	INTERIOR WALL FINISH TO REPAIR
------	--------------------------------



#51:	URINALS
------	---------



#52:	KITCHEN EXHAUST HOOD
------	----------------------



#53:	TROUGH STYLE SINK
------	-------------------



#54:	DRINKING FOUNTAINS
------	--------------------



#55:	DRINKING FOUNTAIN
------	-------------------



#56:	DRINKING FOUNTAIN
------	-------------------



#57:	WATER HEATER
------	--------------



#58:	EXHAUST FAN
------	-------------



#59:	AIR COOLED CONDENSER
------	----------------------



#60:	EXHAUST FAN
------	-------------



#61:	EXHAUST FAN
------	-------------



#62:	VARIABLE AIR VOLUME (VAV) BOX
------	-------------------------------



#63:	INTERIOR AIR HANDLER
------	----------------------



#64:	INTERIOR AIR HANDLER
------	----------------------



#65:	BUILDING AUTOMATION SYSTEM (HVAC CONTROLS)
------	--



#66:	ROOF TOP PACKAGE UNIT
------	-----------------------



#67:	SPLIT SYSTEM HVAC
------	-------------------



#68:	SPLIT SYSTEM HVAC
------	-------------------



#69:	DUCTLESS SPLIT SYSTEM, CONDENSER
------	----------------------------------



#70:	FAN COIL UNIT
------	---------------



#71:	EXTERIOR DOOR
------	---------------



#72:	INTERIOR LIGHTING SYSTEM
------	--------------------------



#73: FLUORESCENT LIGHTING FIXTURE



#74: DISTRIBUTION PANEL



#75: BUILDING/MAIN SWITCHGEAR



#76: SWITCHBOARD AND DISTRIBUTION PANEL



#77: FIRE ALARM CONTROL PANEL



#78: COMMERCIAL 2 DOOR REFRIGERATOR



#79:	WOOD FENCE AND DUMPSTERS
------	--------------------------



#80:	CONCRETE SIDEWALK
------	-------------------



#81:	ASPHALT SIDEWALK
------	------------------



#82:	ASPHALT PAVEMENT
------	------------------



#83:	PLAY STRUCTURE
------	----------------



#84:	PLAY STRUCTURE
------	----------------



#85:	PROPERTY SIGN
------	---------------



#86:	SIDEWALK AND METAL RAILING
------	----------------------------



#87:	PARKING LOT
------	-------------



#88:	SIDEWALK
------	----------



#89:	POLE LIGHTS
------	-------------



#90:	ADA, PARKING
------	--------------

---


---

## Appendix B: Site Plans

---

---

Site Plan



**Project Name:**  
Lawton Elementary


**Source:**  
Google Earth Pro

**Project Number:**  
129010.18R000-016.354

**On-Site Date:**  
March 9, 2018

# LAWTON SCHOOL

2017-2018



MULTI PURPOSE ROOM

KITCHEN

208 VOCAL MUSIC

Schroeder 1st

Whitcomb 2nd

Moore 2nd

Lentz

Gibson 1st

Nowicki 2nd

LOUNGE

215

214 LOCKER ROOM

211

Stewart Gym

Magar Art

Stepnitz KDG

219 SPEECH THERAPIST WORK ROOM

221

222

101

Szalay KDG

Computer Lab

Krause 1st

Ross 4th

Karr

Cruz Y 5's

116 MEDIA CENTER

Peurach

Johnson KDG

Gerhart 5th

Abbot 5th

PRINCIPAL

105 OFFICE

Sunwoo 1st

Raddatz KDG

Cesarz TC  
Simko TC

Wesley 5th

Blick Principal  
Watson Principal  
Brown OP  
Napolitan TC  
Wright OP

---

---

## **Appendix C: Supporting Documentation**

---

---

---

---

**THIS APPENDIX IS INTENTIONALLY LEFT  
BLANK.**

---

---

---

---

## **Appendix D: EMG Accessibility Checklist**

---

---

Property Name: Lawton Elementary  
 EMG Project Number: 129010.18R000-016.354

Abbreviated Accessibility Checklist					
	Building History	Y	N	U	Comments
1	Has an ADA survey previously been completed for this property?			X	
2	Have any ADA improvements been made to the property since original construction?	X			
3	Has building ownership/management reported any ADA complaints or litigation?			X	
	Parking	Y	N	NA	Comments
1	Does the required number of standard ADA designated spaces appear to be provided?	X			With addition of sign
2	Does the required number of van-accessible designated spaces appear to be provided?	X			
3	Are accessible spaces on the shortest accessible route to an accessible building entrance?	X			
4	Does parking signage include the International Symbol of Accessibility?	X			
5	Does each accessible space have an adjacent access aisle?	X			
6	Do parking spaces and access aisles appear to be relatively level and without obstruction	X			
	Exterior Accessible Route	Y	N	NA	Comments
1	Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property?	X			
2	Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances?	X			
3	Are curb ramps present at transitions through raised curbs on all accessible routes?	X			
4	Do curb ramps appear to have compliant slopes for all components?	X			
5	Do ramp runs on an accessible route appear to have compliant slopes?	X			
6	Do ramp runs on an accessible route appear to have a compliant rise and width?	X			
7	Do ramps on an accessible route appear to have compliant end and intermediate landings?	X			
8	Do ramps on an accessible route appear to have compliant handrails?	X			



<b>Building Entrances</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
1	Do a sufficient number of accessible entrances appear to be provided?	X			
2	If the main entrance is not accessible, is an alternate accessible entrance provided?	X			
3	Is signage provided indicating the location of alternate accessible entrances?		X		
4	Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side?	X			
5	Do doors at accessible entrances appear to have compliant hardware?	X			
6	Do doors at accessible entrances appear to have a compliant clear opening width?	X			
7	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them?			X	
8	Do thresholds at accessible entrances appear to have a compliant height?	X			
<b>Interior Accessible Routes and Amenities</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
1	Does an accessible route appear to connect all public areas inside the building?	X			
2	Do accessible routes appear free of obstructions and/or protruding objects?	X			
3	Do ramps on accessible routes appear to have compliant slopes?	X			
4	Do ramp runs on an accessible route appear to have a compliant rise and width?	X			
5	Do ramps on accessible routes appear to have compliant end and intermediate landings?	X			
6	Do ramps on accessible routes appear to have compliant handrails?	X			
7	Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage?			X	
8	Do public transaction areas have an accessible, lowered service counter section?	X			
9	Do public telephones appear mounted with an accessible height and location?			X	
<b>Interior Doors</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
1	Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side?	X			
2	Do doors at interior accessible routes appear to have compliant hardware?	X			



<b>Interior Doors</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>3</b>	Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force?			X	
<b>4</b>	Do doors on interior accessible routes appear to have a compliant clear opening width?	X			
<b>Elevators</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Are hallway call buttons configured with the "UP" button above the "DOWN" button?			X	
<b>2</b>	Is accessible floor identification signage present on the hoistway sidewalls on each level?			X	
<b>3</b>	Do the elevators have audible and visual arrival indicators at the entrances?			X	
<b>4</b>	Do the elevator hoistway and car interior appear to have a minimum compliant clear floor area?			X	
<b>5</b>	Do the elevator car doors have automatic re-opening devices to prevent closure on obstructions?			X	
<b>6</b>	Do elevator car control buttons appear to be mounted at a compliant height?			X	
<b>7</b>	Are tactile and Braille characters mounted to the left of each elevator car control button?			X	
<b>8</b>	Are audible and visual floor position indicators provided in the elevator car?			X	
<b>9</b>	Is the emergency call system at the base of the control panel and does it not require voice communication?			X	
<b>Common Area Toilet Rooms</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Do publicly accessible toilet rooms appear to have a minimum compliant floor area?	X			
<b>2</b>	Does the lavatory appear to be mounted at a compliant height and with compliant knee area?	X			
<b>3</b>	Does the lavatory faucet have compliant handles?	X			
<b>4</b>	Is the plumbing piping under lavatories configured to protect against contact?		X		
<b>5</b>	Are grab bars provided at compliant locations around the toilet?	X			
<b>6</b>	Do toilet stall doors appear to provide the minimum compliant clear width?	X			
<b>7</b>	Do toilet stalls appear to provide the minimum compliant clear floor area?	X			
<b>8</b>	Does minimum one urinal appear to be mounted at a compliant height and with compliant approach width?	X			



<b>Common Area Toilet Rooms</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	
<b>9</b>	Do accessories and mirrors appear to be mounted at a compliant height?	X			
<b>Hospitality</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Does there appear to be adequate clear floor space around the exercise machines/equipment?			X	
<b>2</b>	Does property management report there are a sufficient number of ADA guest rooms without roll-in showers?			X	
<b>3</b>	Does property management report there are a sufficient number of ADA guest rooms with roll-in showers?			X	
<b>4</b>	Does property management report there are a sufficient number of ADA guest rooms with communications features?			X	
<b>5</b>	Does property management report there are a sufficient number of portable communications kits available, where built-in communication features are not provided?			X	
<b>6</b>	Are publicly accessible swimming pools equipped with an entrance lift?			X	
<b>Self- Service Storage</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Does property management report there are a sufficient number of ADA self-service storage units?			X	
<b>2</b>	Does it appear that the accessible unit doors are accessible?			X	

<b>Abbreviated Fair Housing Act and ADA Accessibility Checklist</b>					
<b>History</b>		<b>Y</b>	<b>N</b>	<b>U</b>	<b>Comments</b>
<b>1</b>	Was first residential occupancy at the property after March 13, 1991?			X	
<b>2</b>	Does the property consist of four or more dwelling units in each building			X	
<b>4</b>	Is property management or the owner aware of any areas of accessibility non-compliance resulting in litigation?			X	
<b>Exterior Accessible Route and Building Entrance</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Do designated accessible parking spaces appear to be provided in sufficient number at appropriate locations?	X			
<b>2</b>	Do appropriate transitions from vehicular areas to sidewalks appear to be provided?	X			
<b>3</b>	Do walkway running slopes and cross slopes appear to be compliant and not excessive?	X			
<b>4</b>	Do walkways appear to be the correct width, and clear of obstructions, including overhanging vehicles?	X			



**Abbreviated Fair Housing Act and ADA Accessibility Checklist**

<b>Exterior Accessible Route and Building Entrance</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>5</b>	Do ramps appear to have handrails and edge protection where required?	X			
<b>6</b>	Do building entry points/accessible doors appear to be provided along an apparent accessible route?	X			
<b>7</b>	Do the main entrances appear to be barrier free and readily accessible, without steps, obstacles, or revolving doors required for access?	X			
<b>Accessible Common Areas</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Does a continuous accessible route appear to be provided throughout the property, including the site, parking areas and amenities?	X			
<b>2</b>	Do common area/visitor restrooms appear to be barrier free and readily accessible?	X			
<b>3</b>	Do the amenities appear to be barrier free and readily accessible?	X			
<b>4</b>	Do doors/entries appear to be designed for accessibility?	X			
<b>5</b>	Do interior doors appear to be designed for accessibility?	X			
<b>Covered Units</b>		<b>Y</b>	<b>N</b>	<b>NA</b>	<b>Comments</b>
<b>1</b>	Do the interiors of the "covered" units appear to provide adequate maneuverability?			X	
<b>2</b>	Do the environmental controls within the "covered" units appear to be at appropriate heights/locations?			X	
<b>3</b>	Are reinforcements reportedly provided for future installation of grab bars at appropriate locations in the "covered" units?			X	
<b>4</b>	Do the interior kitchen areas of the "covered" units appear to provide adequate clearances for maneuverability?			X	
<b>5</b>	Do the bathrooms of the "covered" units appear to provide adequate clearances?			X	



---

---

## Appendix E: Pre-Survey Questionnaire

---

---

## EMG FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

**Building / Facility Name:** \_\_\_\_\_

**Name of person completing form:** \_\_\_\_\_

**Title / Association with property:** \_\_\_\_\_

**Length of time associated w/ property:** \_\_\_\_\_

**Date Completed:** \_\_\_\_\_

**Phone Number:** \_\_\_\_\_

**Directions:** Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

DATA OVERVIEW		RESPONSE			
1	Year/s constructed				
2	Building size in SF				
3	Major Renovation Dates	Façade		HVAC	
		Roof		Electrical	
		Interiors		Site Pavement	
		Accessibility		other	
QUESTION		RESPONSE			
4	Provide additional detail about the scope of the MAJOR additions, renovations, or systemic rehabilitations since construction (referenced above in Question 3).				
5	List other significant but somewhat lesser capital improvements, focusing on recent years (provide approximate year completed).				
6	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?				
7	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.				

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
8	Are there any problems with foundations or structures, like excessive settlement?					
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants?					
10	Are there any wall, window, basement or roof leaks?					
11	Are there any plumbing leaks, water pressure, or clogging/back-up problems?					
12	Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service?					
13	Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas?					
14	Is the electrical service outdated, undersized, or otherwise problematic?					
15	Are there any problems or inadequacies with exterior building-mounted lighting?					
16	Is site/parking drainage inadequate, with excessive ponding or other problems?					
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?					
18	ADA: Has an accessibility study been performed at the site? If so, indicate when.					
19	ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part?					
20	ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation?					

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible.

#### INFORMATION REQUIRED

- |   |   |
|---|---|
| <ol style="list-style-type: none"> <li>1. All available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work.</li> <li>2. A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features.</li> <li>3. For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s).</li> <li>4. For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet.</li> <li>5. For hotel or nursing home properties, provide a summary of the room types and room type quantities.</li> <li>6. Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents.</li> <li>7. The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies.</li> </ol> | <ol style="list-style-type: none"> <li>8. The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors.</li> <li>9. A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements.</li> <li>10. Records of system &amp; material ages (roof, MEP, paving, finishes, furnishings).</li> <li>11. Any brochures or marketing information.</li> <li>12. Appraisal, either current or previously prepared.</li> <li>13. Current occupancy percentage and typical turnover rate records (for commercial and apartment properties).</li> <li>14. Previous reports pertaining to the physical condition of property.</li> <li>15. ADA survey and status of improvements implemented.</li> <li>16. Current / pending litigation related to property condition.</li> </ol> |
|---|---|

Your timely compliance with this request is greatly appreciated.