



Ann Arbor Public Schools
Drinking Water Analysis
Project Number: AE240030

Site: Eberwhite Elementary School									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: February 24, 2024									
Sampler: Dean Johnson									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Eberwhite-04	Room 127, Combination Sink, Glass Filler	Combination Sink	4:23 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-09	Hallway, Outside Room 122, Left Stainless Glass Filler	Glass Filler	4:27 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-15	Hallway, Outside Library, Hydration Station, Bottle Fill	Hydration Station	4:54 PM	5	ND	Y	Y	N/A	
Eberwhite-19	Room 120, Combination Sink, Glass Filler	Combination Sink	4:32 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-22	Room 131, Combination Sink, Glass Filler	Combination Sink	4:20 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-31	Room 134, Combination Sink, Glass Filler	Combination Sink	4:15 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-37	Hallway, Outside Room 106, Refrigerated Glass Filler	Water Cooler	4:37 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-40	Room 106, Combination Sink, Glass Filler	Combination Sink	4:41 PM	5	ND	Y	Y	7/3/2023	Filter expired - should be replaced.
Eberwhite-42	Gym, Right Wall Glass Filler	Glass Filler	4:50 PM	5	ND	Y	N	N/A	

*ND = Non-Detected at Reported Detection Limit of 1 ug/L