

Ann Arbor Public Schools Drinking Water Analysis Project Number: AE230030

Wines Elementary School

Date of Sampling: January 3, 2023

Sampler: Victoria Heed

Sample #	Location	Type ¹	Time Collected	District Lead Action Level (ug/L) ²	I I ead Results	Aerator Present Y/N	POU Filter Present Y/N	Filter Date/Color	Notes
Wines ES-02	Room 114, Combination Sink, Glass Filler	С	11:48 AM	5	ND ³	N	Y	7/20/2022	Initial First Draw, Filtered.
Wines ES-03	Room 116, Combination Sink, Glass Filler	С	11:51 AM	5	ND	Ν	Υ	7/20/2022	Initial First Draw, Filtered.
Wines ES-07	Room 119, Combination Sink, Glass Filler	С	11:56 AM	5	ND	N	Υ	7/20/2022	Initial First Draw, Filtered.
Wines ES-09	Gym, Right Glass Filler	G	11:45 AM	5	ND	N	Υ	Unknown Filter Date	Initial First Draw, Filtered.
	Kitchen, 3-Compartment, Add On Faucet, Far Right Faucet, Kitchen Faucet	KF	12:19 PM	5	ND	Y	Υ	7/19/2022	Initial First Draw, Filtered.

¹⁾ Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

 $^{2) \} https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf$

³⁾ ND = Non-Detected at Reported Detection Limit of 1 ug/L



Ann Arbor Public Schools Drinking Water Analysis Project Number: AE230030

Wines Elementary School

Date of Sampling: January 3, 2023

Sampler: Victoria Heed

Sample #	Location	Type ¹	Time Collected	District Lead Action Level (ug/L) ²	Head Recults	Aerator Present Y/N	POU Filter Present Y/N	Filter Date/Color	Notes
Wines ES-26	Student Workroom, Across from Gym, Combination Sink, Glass Filler	С	12:15 PM	5	ND	N	Υ	7/19/2022	Initial First Draw, Filtered.
Wines ES-31	Room 111, Combination Sink, Glass Filler	С	12:01 PM	5	ND	Ν	Υ	7/19/2022	Initial First Draw, Filtered.
1 Wines FS-39	Room 107, Combination Sink, Glass Filler	С	12:04 PM	5	ND	N	Υ	7/19/2022	Initial First Draw, Filtered.
Wines ES-43	Room 104, Combination Sink, Glass Filler	С	12:06 PM	5	ND	N	Υ	7/19/2022	Initial First Draw, Filtered.
Wines ES-57	Room 101, Left Combination Sink, Glass Filler	С	12:11 PM	5	ND	N	Υ	7/19/2022	Initial First Draw, Filtered.

¹⁾ Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

 $^{2) \} https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf$

³⁾ ND = Non-Detected at Reported Detection Limit of 1 ug/L



Ann Arbor Public Schools Drinking Water Analysis Project Number: AE230030

Wines Elementary School

Date of Sampling: January 3, 2023

Sampler: Victoria Heed

Sample #	Location	Type ¹	Time Collected	District Lead Action Level (ug/L) ²	Lead Results	Aerator Present Y/N	POU Filter Present Y/N	Filter Date/Color	Notes
I Wines ES-60	Athletic Storage, Hydration Station, Bottle Fill	HS	11:42 AM	5	ND	Y	Υ	No Filter Light	Initial First Draw, Filtered.
Wines ES-67	Hallway, Outside Room 117, Hydration Station, Bottle Fill	HS	11:53 AM	5	ND	Y	Y	Green	Initial First Draw, Filtered.
Wines ES-66	Hallway, Outside Room 103, Hydration Station, Bottle Fill	HS	12:08 PM	5	ND	Y	Υ	Green	Initial First Draw, Filtered.

¹⁾ Type: B = Bubbler, HS = Hydration Station, BT = Single Bottle Fill, WC = Single Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, PB = Potable Bathroom Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee Machine, G = Glass Filler

 $^{2) \} https://www.epa.gov/sites/default/files/2016-06/documents/npwdr_complete_table.pdf$

³⁾ ND = Non-Detected at Reported Detection Limit of 1 ug/L