



**Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030**

Site: Slauson Middle School									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: June 18, 2024									
Sampler: Teagan Evans									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Slauson-02	Hallway, Outside of Lower Gym, Hydration Station, Bottle Fill	Hydration Station	8:51 AM	5	ND	Y	Y	N/A	
Slauson-12	Men's Pool Locker Room, Bubblers, Glass Filler	Bubbler	8:54 AM	5	ND	Y	N	N/A	
Slauson-26	Auditorium Lobby, Water Cooler, Glass Filler	Water Cooler	9:13 AM	5	ND	Y	N	N/A	
Slauson-33	Hallway, Outside of Room 138, Hydration Station, Bottle Fill	Hydration Station	8:59 AM	5	ND	Y	Y	N/A	
Slauson-36	Hallway, Outside of Room 146, Right Refrigerated Glass Filler	Glass Filler	N/A	5	N/A	Y	N	N/A	No sample taken. Slauson-36 was previously used, alternate fixture Slauson-10 sampled.
Slauson-10	Room 138, Two Compartment Sink, Faucet	Kitchen Faucet	10:02 AM	5	1	Y	N	N/A	Alternate sample for Slauson-36.

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L



**Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030**

Site: Slauson Middle School									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: June 18, 2024									
Sampler: Teagan Evans									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
Slauson-40	Room 321, Science Room, Faucet	Faucet	N/A	5	N/A	Y	N	N/A	Not sampled. Science rooms are not sampled for there is no eating or drinking allowed in these rooms. Alternate fixture Slauson-47 sampled.
Slauson-47	Hallway, Outside Room 348, Water Cooler, Glass Filler	Water Cooler	9:40 AM	5	ND	Y	N	N/A	Alternate sample for Slauson-40.
Slauson-43	Hallway, Outside Library Lounge, Left Hydration Station, Bottle Fill	Hydration Station	9:21 AM	5	ND	Y	Y	N/A	
Slauson-46	Hallway, Outside Room 348, Hydration Station, Bottle Fill	Hydration Station	N/A	5	N/A	Y	Y	N/A	Not sampled. No flow at bottle fill. Alternate fixture Slauson-50 sampled.
Slauson-50	Hallway, Outside Room 348, Hydration Station, Bubbler	Hydration Station	9:50 AM	5	ND	Y	Y	N/A	Alternate sample for Slauson-46.

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L