



Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030

Site: Ann Arbor Open at Mack									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: February 10, 2024									
Sampler: Stephanie Waranauckas									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
A2SOM-23	Staff Lounge, Single Sink, Faucet	Faucet	1:10 PM	5	ND	Y	Y	8/22/2023	
A2SOM-30	Hallway, Left of Dining Room 202, Hydration Station, Bottle Fill	Hydration Station	1:25 PM	5	ND	Y	N	N/A	
A2SOM-36	Room 237, Combination Sink, Bubbler	Combination Sink	1:30 PM	5	ND	Y	Y	8/26/2023	
A2SOM-42	Room 243, Combination Sink, Glass Filler	Combination Sink	1:35 PM	5	ND	Y	Y	8/26/2023	
A2SOM-48	Room 249, Combination Sink, Glass Filler	Combination Sink	1:40 PM	5	ND	Y	Y	8/26/2023	
A2SOM-52	Room 253, Combination Sink, Glass Filler	Combination Sink	1:45 PM	5	ND	Y	Y	8/26/2023	

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L



Ann Arbor Public Schools  
Drinking Water Analysis  
Project Number: AE240030

Site: Ann Arbor Open at Mack									
Sampling Type: Initial First Draw Sampling (IFD)									
Date of Sampling: February 10, 2024									
Sampler: Stephanie Waranauckas									
Sample #	Location	Fixture Type	Time Collected	District Lead Action Level (ug/L)	Lead Results (ug/L)	Aerator Present Y/N	POU Filter Present Y/N	Filter Date	Notes
A2SOM-58	Room 259, Combination Sink, Glass Filler	Combination Sink	1:55 PM	5	ND	Y	Y	8/26/2023	
A2SOM-62	Hallway, Floor 3, Outside Room 302/304, Hydration Station, Bottle Fill	Hydration Station	2:05 PM	5	ND	Y	N	N/A	
A2SOM-27	Hallway, Between Mens and Womens Locker Rooms and Doors to the School, Hydration Station, Bottle Fill	Hydration Station	1:17 PM	5	ND	Y	N/A	N/A	

\*ND = Non-Detected at Reported Detection Limit of 1 ug/L