

| Allen Elementary School | | | | | | | | | |
|--------------------------|--|-------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--|--|--|
| Date of Sampling: 11/3/2 | 2018 | | | | | | | | |
| Sampler: Steven Ripley | | | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes | | |
| Allen-01 | Staff Lounge, Faucet | KF | 10:35 AM | 5 | ND ³ | Y | First Draw | | |
| Allen-02 | Room K-3, Bubbler | С | 11:20 AM | 5 | ND | N | First Draw | | |
| Allen-03 | Room CL-8, Bubbler | С | 10:41 AM | 5 | ND | N | First Draw | | |
| Allen-04 | Room C-10, Faucet | С | 11:06 AM | 5 | 1 | Y | First Draw | | |
| Allen-05 | Hallway Outside of Computer Lab, Bottle Fill, Water Cooler | вт | 10:32 AM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-06 | Room A-14, Faucet | С | 11:36 AM | 5 | 1 | Y | First Draw | | |
| Allen-07 | Room A-17, Bubbler | С | 11:52 AM | 5 | 1 | N | First Draw | | |
| Allen-08 | Room A-18, Bubbler | С | 11:50 AM | 5 | ND | N | First Draw | | |
| Allen-09 | Room A-20, Faucet | С | 11:42 AM | 5 | ND | Y | First Draw | | |
| Allen-10 | Hallway Outside Men's Bathroom Near Gym, Right Water Cooler | wc | 11:55 AM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-11 | Room B-22, Bubbler | С | 11:58 AM | 5 | ND | N | First Draw | | |
| Allen-12 | Kitchen, 3-Compartment, Right Faucet | KF | 9:55 AM | 5 | ND | Y | First Draw | | |
| Allen-13 | Room A-17, Faucet | C | 11:52 AM | 5 | 1 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-14 | Room A-18, Faucet | С | 11:50 AM | 5 | 4 | Y | First Draw | | |
| Allen-15 | Room A-16, Bubbler | С | 11:45 AM | 5 | ND | N | First Draw | | |
| Allen-16 | Room A-16, Faucet | С | 11:45 AM | 5 | ND | Y | First Draw | | |
| Allen-17 | Room A-19, Bubbler | С | 11:47 AM | 5 | ND | N | First Draw | | |

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante

3) ND = Non Detected at Reported Detection Limit of 1 ug/L



| Allen Elementary School | | | | | | | | | |
|-------------------------|---|-------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--|--|--|
| Date of Sampling: 11/3/ | 2018 | | | | | | | | |
| Sampler: Steven Ripley | | | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes | | |
| Allen-18 | Room A-19, Faucet | С | 11:48 AM | 5 | 1 | Y | First Draw | | |
| Allen-19 | Room A-15, Bubbler | С | 11:40 AM | 5 | ND | N | First Draw | | |
| Allen-20 | Room A-15, Faucet | С | 11:40 AM | 5 | 2 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-21 | Room A-20, Bubbler | С | 11:43 AM | 5 | ND | N | | | |
| Allen-22 | Room A-14, Bubbler | С | 11:35 AM | 5 | ND | N | First Draw | | |
| Allen-23 | Room C-5, Faucet | С | 10:48 AM | 5 | 2 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-24 | Room A-21, Bubbler | С | 11:31 AM | 5 | ND | N | First Draw | | |
| Allen-25 | Room A-21, Faucet | С | 11:33 AM | 5 | 2 | Y | First Draw | | |
| Allen-26 | Hallway, Across From Library Adjacent to Bathrooms, Water Cooler | WC | 10:40 AM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-27 | Room C-12, Bubbler | С | 11:00 AM | 5 | ND | N | First Draw | | |
| Allen-28 | Room C-12, Faucet | С | 11:00 AM | 5 | 2 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-29 | Room C-11, Bubbler | С | 11:03 AM | 5 | ND | N | First Draw | | |
| Allen-30 | Room C-11, Faucet | С | 11:04 AM | 5 | 1 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-31 | Room C-10, Bubbler | С | 11:07 AM | 5 | 11 | N | First Draw | | |
| Allen-32 | Room C-9, Bubbler | С | 11:10 AM | 5 | ND | N | First Draw | | |
| Allen-33 | Room C-9, Faucet | C | 11:10 AM | 5 | ND | Y | First Draw | | |
| Allen-34 | Hallway between Rooms K-3 and K-4, Water Cooler | wc | 11:13 AM | 5 | ND | N | First Draw. Minor Corrosion on Mouthpiece. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante 3) ND = Non Detected at Reported Detection Limit of 1 ug/L



| Allen Elementary School | | | | | | | | | |
|-------------------------|---|-------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--|--|--|
| Date of Sampling: 11/3/ | | | | | | | | | |
| Sampler: Steven Ripley | | | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes | | |
| Allen-35 | Room K-4, Bubbler | С | 11:15 AM | 5 | ND | N | First Draw | | |
| Allen-36 | Room K-4, Faucet | С | 11:16 AM | 5 | 1 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-37 | Room K-3, Faucet | С | 11:20 AM | 5 | 3 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-38 | Room K-2, Bubbler | C | 11:26 AM | 5 | 1 | N | First Draw | | |
| Allen-39 | Room K-2, Faucet | С | 11:26 AM | 5 | ND | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-40 | Room K-1, Bubbler | С | 11:23 AM | 5 | ND | N | First Draw | | |
| Allen-41 | Room K-1, Faucet | С | 11:23 AM | 5 | 2 | Y | First Draw | | |
| Allen-42 | Hallway Across B-22, Bottle Fill | BT | 11:54 AM | 5 | 1 | Y | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-43 | Hallway Across B-22, Bottle Fill, Water Cooler | BT | 11:58 AM | 5 | ND | N | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-44 | Room B-22, Faucet | С | 12:00 PM | 5 | 2 | Y | First Draw | | |
| Allen-45 | Room B-23, Bubbler | С | 12:00 PM | 5 | ND | N | First Draw | | |
| Allen-46 | Room B-23, Faucet | С | 12:03 PM | 5 | 1 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-47 | Room B-24, Bubbler | С | 12:03 PM | 5 | ND | N | First Draw | | |
| Allen-48 | Room B-24, Faucet | С | 12:05 PM | 5 | ND | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-49 | Room B-25, Bubbler | С | 12:05 PM | 5 | ND | N | First Draw | | |
| Allen-50 | Room B-25, Faucet | С | 10:20 AM | 5 | 1 | Y | First Draw | | |
| Allen-51 | Kitchen, 3-Compartment, Left Faucet | KF | 10:33 AM | 5 | 1 | Y | First Draw | | |

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee

2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante

3) ND = Non Detected at Reported Detection Limit of 1 ug/L



| Allen Elementary School | | | | | | | | | |
|-----------------------------|---|-------------------|-------------------|---------------------------------------|---------------------------|---------------------------|--|--|--|
| Date of Sampling: 11/3/2018 | | | | | | | | | |
| Sampler: Steven Ripley | | | | | | | | | |
| Sample # | Location | Type ¹ | Time Collected | Internal Action Level (ug/L) | Lead Results (ug/L) | Aerator Present Y/N | Notes | | |
| Allen-52 | Hallway Outside of Computer Lab, Bottle Fill | вт | 10:41 AM | 5 | ND | Y | First Draw. Water cooler was reviewed against the EPA Fact Sheet to determine that it is not a lead lined. | | |
| Allen-53 | Room CL-8, Faucet | С | 10:43 AM | 5 | 2 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-54 | Room CL-7, Bubbler | С | 10:44 AM | 5 | 1 | N | First Draw | | |
| Allen-55 | Room CL-7, Faucet | С | 10:45 AM | 5 | 2 | Y | First Draw. Minor Corrosion on Aerator. | | |
| Allen-56 | Room CL-6, Bubbler | С | 10:46 AM | 5 | 3 | N | First Draw | | |
| Allen-57 | Room CL-6, Faucet | С | 10:51 AM | 5 | 5 | Y | First Draw | | |
| Allen-58 | Room CL-5, Bubbler | С | 10:51 AM | 5 | 1 | N | First Draw | | |

1) Type: B = Bubbler, BT = Bottle Fill/Cooler, WC = Water Cooler, C = Combination Sink, F = Faucet, KF = Kitchen Faucet, I = Ice Machine, KK = Kitchen Kettle, PC = Plumed Coffee 2) https://www.epa.gov/your-drinking-water/table-regulated-drinking-water-contaminante 3) ND = Non Detected at Reported Detection Limit of 1 ug/L